

SINGATAC

ENGINEERING PTE LTD

YOUR 24X7 SOLUTION TO KEEP
THE SHIPS SAFE & SAIL ON!

We Make Things Happen!

Brief Profile

- 1997 : Singatac Engineering Pte Ltd was incorporated. Started a small outfit of less than 20 people and did basic sub-contract work in steel repair for ships in shipyards.
- 1998 : Rented a 4000ft² factory to carry out small scale fabrication for ship owners.
- 2000 : Upgraded & rented a 10,000ft² to fabricated bigger structures. Manpower increased to over 150 men.
- 2002 : Further upgraded & bought a 60,000ft² factory.
- 2005 : Added a seafront 100,000ft² yard.
- 2007 : Manpower increased to 600 men. Expanded overseas to Bintan, Indonesia.
- 2008 : Added another 120,000ft² rental factory space in Bintan, Indonesia.
- 2009 : Acquired a seafront yard of 700,000ft² in Bintan, Indonesia.
- 2011 : Brought in 2 dredgers to Bintan anchorage for 2-month refit.
- 2012 : Completed construction of 10m depth heavy duty wharf in the Bintan yard. Brought in the first heavy lift vessel alongside the yard. Downsized manpower in Singapore to 150 men. Upsized manpower in Bintan to 180 men.
- 2015 : Manpower in Bintan boosted to 500 men.

Services




- Repair of hull damages due to collisions, mechanical contacts & corrosion
- Pipe fabrication & installation
- Fabrication, supply & installation of outfitting
- Repair, renewal & testing of machineries
- Cleaning & painting

Typical Works Carried Out (1/4)



Deck Crane Repair



Propeller Repair



New Crane Column



New Gypsy Wheel



New End Covers



New Boiler Shell



Shipside Painting



Car Carrier Ramp door
Repair

Typical Works Carried Out (2/4)




Riding Crew on Voyage
Repair



Anchor & Chain Renewal



Cell Guide Repair



New Crane Jib



In-Situ Crane Heel Pin Repair



Windlass Repair



Recovery of Lost Anchor
Chain



Installation of Mooring
Arrangement

Typical Works Carried Out (3/4)



Pipe Fabrication



Pipe Installation




New Sighting Ports



Container Sockets Renewal



Rudder Repair



Steel Renewal



PBCF Installation



Steel Renewal

Typical Works Carried Out (4/4)



Side Shell Renewal



Hatch Cover Repair



Damage Repair



Bow Damage Repair



Installation of Outriggers



Alongside Repair



Chain cleaning at OPL



Bollard Fabrication

Facilities & Equipment & Manpower (1/2)

□ Fully-Equipped Workshops



Bintan, Indonesia
70,000m² yard c/w 200m waterfront
for vessel upto LOA 200m & draft 8m
(zero tide). Crane capacity up to 350
ton.

Tuas, Singapore
10,000m² yards c/w 100m waterfront
for vessel upto LOA 100m & draft 2m (zero
tide). Crane capacity up to 350 ton.



Facilities, Equipment & Manpower (2/2)

- MANPOWER

Over 600 experienced and skilled employees in ship repairs including engineers, foremen, welders, fitters, riggers, scaffolders, painters, HSE officers, etc.

- CLASS-APPROVED WELDING PROCEDURES

Full range covering carbon steel (Y/S 275~690), pipes (API 5L Gr. A/B to X60), stainless steel (304/316), low-temp steel, aluminium, etc.

- EQUIPMENT

In-house precision machining, steel forming (1" rolling & 1000T pressing), CNC cutting, welding machines (SMAW, GMAW, GTAW, SAW), scaffolding, grit-blasting/spray painting equipment, 250T transporter, 50T~350T crawler cranes, cargo boat, crew boats, fenders, 18m-boomlifts, etc.


- QUALITY SYSTEM

All works will be carried in compliance with DNV-approved ISO 9000.

- SAFETY SYSTEM

All works will be carried in compliance with Singapore Ministry of Manpower's WSH Regulations and BizSafe Programme.

Bintan Industrial Estate, Indonesia



A 4000-ha fully integrated industrial estate established since 1994. Major shareholders included Salim Group & Sembawang Group. Supported by Economic Development Board of Singapore under G2G initiative.

Bintan Industrial Estate, Indonesia



Deck Crane Repair Alongside
Singatac Wharf



Propeller Repair at Bintan IPL



Repair of Dredgers at Bintan
IPL



Repair Alongside Singatac
Wharf



Repair Alongside Singatac
Wharf



Repair Alongside Singatac
Wharf

Bintan Industrial Estate, Indonesia



Repair at Bintan IPL



Repair at Bintan IPL



Alongside
Singatac
Wharf



Alongside
Singatac
Wharf

Bintan Industrial Estate, Indonesia



Cold/Warm Stacking
at Bintan IPL
Anchorage, Indonesia

Major Strengths

- Strong control of internal production resources, ie. manpower, equipment & facilities to provide 24x7 services.
- Very focus in the ship repair business, and we continue to reinvest into the business.
- Top-rate financial footing. We have zero debt.
- Dedicated, committed and highly professional team.
- Strategically ahead of competitors.
- Strong belief in getting the job done right.

Contact Us

SINGAPORE OFFICE:

No. 26 Tuas Avenue 10

Singapore 639147

Tel: (65) 68979566 Email: info@singatac.com.sg

BINTAN OFFICE:

Singatac Offshore Centre

Lot 2 Bintan Industrial Estate

Bintan, Kepulauan Riau 29154, Indonesia

Tel: (62) 770 696 788/789 Email: soc@singatac.com.sg

THE END. THANK YOU.